

Re-Certification & Service Costs for TPI Flue Gas Analysers

<u>709R, 717R & 716</u>			<u>716 c/w NOX fitted</u>			<u>DC710 & DC710C1 Kits</u>			<u>DC710C2 Kit</u>					
<u>Years After Initial Despatch</u>			<u>Cost inc. Return Carraige</u>			<u>Cost inc. Return Carraige</u>			<u>Years After Initial Despatch</u>			<u>Cost inc. Return Carraige</u>		
1	£85.00		£170.00			1	£85.00		£95.00					
2	£85.00		£170.00			2	£85.00		£95.00					
3	£85.00		£170.00			3	£85.00		£95.00					
4	£85.00		£170.00			4	£85.00		£95.00					
5	£85.00		£170.00			5	£85.00		£95.00					
6	£185.00		£270.00			6	£185.00		£195.00					
7	£85.00		£170.00			7	£85.00		£95.00					
8	£85.00		£170.00			8	£85.00		£95.00					
9	£85.00		£170.00			9	£85.00		£95.00					
10	£85.00		£170.00			10	£85.00		£95.00					
11	£85.00		£170.00			11	£85.00		£95.00					
12	£185.00		£270.00			12	£185.00		£195.00					

Any missed annual service(s) may incur a pro-rata charge to cover additional checks/parts which may need to be performed/replaced that are deemed necessary due to these checks/parts not being performed or replaced during previous missed annual service(s).

The above costs are a minimum cost per service. Further costs may be applicable should it be deemed that a component needs to be cleaned, replaced or repaired outside of the terms of the warranty.

The 6 Year Warranty is subject to each of the above annual service/calibrations being carried out by TPI Europe Ltd (or one of their approved Service Centres). Failure to have any of the annual service/calibrations performed will invalidate the warranty. Please note that annual service/calibration is a requirement as set out in BS7967.

Any of the above costs are subject to change at the discretion of TPI Europe Ltd without prior written notification.

All of the above prices are exclusive of VAT and effective from 1st January 2020

TPI Europe Ltd

Unit 6, Rutherford Way Industrial Estate
Crawley, West Sussex. RH10 9LN
Tel: +44 (0) 1293 530196

sales@tpieurope.com
service@tpieurope.com

Any missed annual service(s) may incur a pro-rata charge to cover additional checks/parts which may need to be performed/replaced that are deemed necessary due to these checks/parts not being performed or replaced during previous missed annual service(s).

The above costs are a minimum cost per service. Further costs may be applicable should it be deemed that a component needs to be cleaned, replaced or repaired outside of the terms of the warranty.

The 5 Year Warranty is subject to each of the above annual service/calibrations being carried out by TPI Europe Ltd (or one of their approved Service Centres). Failure to have any of the annual service/calibrations performed will invalidate the warranty. Please note that annual service/calibration is a requirement as set out in BS7967.

SP620 Manometer must be returned at same time as DC710 when included in DC710C2 Kit calibration costs. If SP620 is returned separately then Standard Manometer Calibration Costs will apply.

Any of the above costs are subject to change at the discretion of TPI Europe Ltd without prior written notification.

All of the above prices are exclusive of VAT and effective from 1st January 2020

